



## Sealing washer




### Application

The flat seal between the sealing plate and the extrusion end or a sealing washer between the junction plates and the side of the extrusion guarantees a seal up to 6 bar.

### Specification

Black nitrile rubber  
70 shore A

## Junction plates



### Application

High pressure junction plate for side connections (> 6 bar). The thread for the junction is normally tapped directly into the side of the extrusion. No junction plates are required for side connections to the 40x80 extrusion.

### Fixing kit\*

Screws + threaded plates

### Specification

Al, anodised in natural colours  
1/4" gas connection



Order data	Order number	Order data	Order number
------------	--------------	------------	--------------

### Junction plate sealing washer

50x100 extrusion	A80-41
50x150 extrusion (2 x)	A80-42

### Junction plate

	A	B	C	D	E	F	G	Order number
50x100 extrusion	50	100	50	-	25	50	-	A80-40*
50x150 extrusion	50	150	50	50	25	50	50	A80-50*

\* Fixing kit: add -S to the order number  
Example: C80-40-S